



2015 Mercedes-Benz B-Class 4dr HB Electric Drive

WDDVP9AB4FJ006690 | 26,678 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Textile

Lane/Run 11/45 | Facilitation Manheim San Francisco Bay | Seller MERCEDES-BENZ FINANCIAL



AVERAGE
3.9
Average



Damages



No Structural
Damage



No Prior
Paint



Tires



Clean



Drivable



Starts



No Odor



Keys | Fobs
2 | 0



Title? (No
Data)

Announcements

- DMV\$230
- CLEAN CARFAX
- No Sunroof

High Value Options






- Back-Up Camera
- Blind Spot Monitor
- Bluetooth Connection
- HID headlights
- Integrated Turn Signal Mirrors
- Keyless Start
- Navigation System
- Power Driver Seat
- Power Passenger Seat
- Premium Sound System
- Rain Sensing Wipers
- Satellite Radio
- Seat Memory
- Smart Device Integration
- Tire Pressure Monitor
- Woodgrain Interior Trim

Damage Overview

None ● ● ● ● Severe

● Structural Issue

Exterior (6)

Description	Condition Severity	Type	Image	Additional Info
● F Bumper Center Molding	Broken Replacement Required	Miscellaneous		
● Front Bumper Cover	Curb Rash 7" to 8"	Paint and Body Requires Conventional Repair		
● LF Wheel	Curb Rash 2" to 3"	Miscellaneous		
● L Qtr Panel	Dent/Paint Dmg 2" to 3"	Minor Damages Conventional Repairs May Be Required		
● Rear Bumper Cover	Heavy Mult Scratches 4	Paint and Body Requires Conventional Repair		
● R Qtr Panel	Heavy Mult Scratches 3	Paint and Body Requires Conventional Repair		

Interior (1)

Description	Condition Severity	Type	Image	Additional Info
● Steering Wheel	Worn Acceptable	Mechanical		

Structure (0)

No structural damages reported

Other (0)

No other damages reported

Tires & Wheels

Wheels Aluminum

Left Front

MICHELIN

5/32"





225/50R17.0


Left Rear

MICHELIN

8/32"

225/50R17.0

-  6/32 +
-  5/32 to 4/32
-  < 4/32
-  N/A



Right Front

MICHELIN

7/32"

225/50R17.0

Right Rear

MICHELIN

5/32"

225/50R17.0

Spare

(None)

0/32"

History



No. of Historical Events	7
Last Reported Event Date	03/25/2019
Calculated Owners	1
Last Reported Mileage	26,678
Calculated Accidents	0

Title and Problem Check  Vehicle checks out!

Odometer Check  Vehicle checks out!

Use and Event Check  Specific vehicle use(s) or events reported

AutoCheck Buyback Protection  Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color

Universe Blue Metallic

894

Interior Color

Black

Top Type

Hard Top

MSRP

Not Available

Title State

CA

Title Received

12/07/2018

Received Date

12/04/2018

Inspection Location

Manheim San Francisco Bay

Work Order

2316660

In Service Date

Not Available

Org Mfg Basic Warranty

Not Available

*Manheim is not responsible for voided warranties

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Automatic Headlights
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- CD Player
- Cruise Control
- Daytime Running Lights
- Driver Adjustable Lumbar
- Driver Air Bag

- Driver Illuminated Vanity Mirror
- Driver Vanity Mirror
- Engine Immobilizer
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- HD Radio
- Heated Mirrors
- Intermittent Wipers
- Keyless Entry
- Knee Air Bag
- Leather Steering Wheel
- Mirror Memory
- MP3 Player
- Pass-Through Rear Seat
- Passenger Adjustable Lumbar
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Illuminated Visor Mirror
- Passenger Vanity Mirror
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Floor Mats
- Rear Head Air Bag
- Rear Side Air Bag
- Rear Spoiler
- Stability Control
- Steering Wheel Audio Controls
- Telematics
- Traction Control
- Trip Computer
- Universal Garage Door Opener
- Variable Speed Intermittent Wipers

Interior

- Odometer Operable
- Textile

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Infrared - 2

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,320,362

VIN: WDDVP9AB4FJ006690,

Work Order: 2316660

© 2019 Manheim. All Rights Reserved

[Return to the classic CR](#)